

## QDRIVES VERIFIED CERTIFICATION

Q Drives Automotive Private Limited  
CIN: U45101TS2026PTC214865 GSTIN: 36AABCQ2618Q1Z1  
www.qdrives.net | +91 89779 86662 | Hyderabad, India

QD

REPORT ID  
**QD-FU4HPH**

REPORT TYPE  
**PDI Inspection**

GENERATED DATE  
**01 Jun 2026**

INSPECTOR  
**Nihad**

REGISTRATION  
**TG10\*\*\*\*\***

INSPECTION DATE  
**31 May 2026**

### ● QDRIVES CERTIFIED

OVERALL GRADE <b>A+</b>	CONDITION SCORE <b>92.7 / 100</b>	OVERALL CONDITION <b>● Excellent Condition</b>	BUYER RECOMMENDATION <b>Recommended Purchase</b>
----------------------------	--------------------------------------	---	---

### VEHICLE SUMMARY

Make / Model	<b>MAHINDRA XUV700</b>
Variant	<b>AX7 DSL</b>
Year	<b>2025</b>
Fuel	<b>Diesel</b>
Transmission	<b>Manual</b>
Kilometres Driven	<b>28,500 km</b>
Rim Size	<b>18 inch</b>
E20 Compatible	<b>Yes</b>
Registration Number	<b>TG10*****</b>
Registration Date	<b>17 Jun 2025</b>
Registration Validity	<b>30 Jun 2040</b>
Tax Paid Upto	<b>09 Jun 2037</b>
RTA Registering Authority	<b>RTA Hyderabad-NZ</b>
VIN / Chassis Number	<b>MA1N*****</b>
Engine Number	<b>ZSS4*****</b>
Ownership	<b>1st Owner</b>

### KEY FINDINGS

- Bonnet repainted (134 µm) — cosmetic repair detected.

### EXTERIOR / BODY CONDITION

Panel	Reading (µm)	Interpretation
Bonnet	134 µm	● Repainted
Left Front Fender	96 µm	● OEM Paint
Left Front Door	90 µm	● OEM Paint
Left Rear Door	91 µm	● OEM Paint
Left Rear Quarter	92 µm	● OEM Paint

This inspection reflects the visible and accessible condition of the vehicle at the time of inspection. Components not accessible without dismantling have not been evaluated. Findings are intended to assist buyers in making informed decisions and do not constitute a mechanical warranty or guarantee.

## QDRIVES VERIFIED CERTIFICATION

Q Drives Automotive Private Limited  
CIN: U45101TS2026PTC214865 GSTIN: 36AABCQ2618Q1Z1  
www.qdrives.net | +91 89779 86662 | Hyderabad, India



Boot	92 µm	● OEM Paint
Roof	102 µm	● OEM Paint
Right Rear Quarter	98 µm	● OEM Paint
Right Rear Door	87 µm	● OEM Paint
Right Front Door	90 µm	● OEM Paint
Right Front Fender	95 µm	● OEM Paint

Body Remarks: Check photos, Bonnet repainted from Showroom before delivery

### STRUCTURE & FACTORY FITMENT

Bonnet Bolts	<b>OEM</b>
Door Bolts	<b>OEM</b>
Chassis Rails	<b>OEM</b>
Pillars	<b>OEM</b>
Engine Bay Welds	<b>OEM</b>
Boot Floor	<b>OEM</b>
Airbags	<b>OEM</b>

### GLASS

Windshield	<b>Original</b>
Side Glasses	<b>Original</b>
Rear Glass	<b>Original</b>

### BATTERY

Battery Brand	<b>Mahindra</b>
Battery Age	<b>8 months</b>
Voltage	<b>12.5 V — ● Operating Normally</b>

### TYRES & WHEELS

Tyre	Brand	Mfg	Tread (mm)	Condition
Front Left	Bridgestone	W50/2024	5 mm	● Good
Front Right	Bridgestone	W50/2024	4 mm	● Moderate Wear
Rear Left	Bridgestone	W50/2024	5 mm	● Good
Rear Right	Bridgestone	W50/2024	6 mm	● Good
Spare Wheel	Bridgestone	W50/2025	6 mm	● Good

Matching Tyres **Yes**

This inspection reflects the visible and accessible condition of the vehicle at the time of inspection. Components not accessible without dismantling have not been evaluated. Findings are intended to assist buyers in making informed decisions and do not constitute a mechanical warranty or guarantee.

## QDRIVES VERIFIED CERTIFICATION

Q Drives Automotive Private Limited  
CIN: U45101TS2026PTC214865 GSTIN: 36AABCQ2618Q1Z1  
www.qdrives.net | +91 89779 86662 | Hyderabad, India



Uneven Wear	No
Sidewall Damage	No
Alignment Wear	No
Alloy Wheel Condition	Good
Wheel Damage	No
Wheel Balancing	OK

### ENGINE & GEARBOX

Engine Oil Level	Full
Engine Oil Condition	Dirty
Cold Start	● A+
Engine Noise	● A+
Gear Shift Quality	● A+
Clutch Operation	● A+
Turbo Condition	● A+
Engine Mounts	● A+
Fluid Leaks	● A+

### SUSPENSION & BRAKES

Suspension	● A+
Steering	● A+
Brakes	● A+

### AIR CONDITIONING

Cooling	● A+
Compressor	● A+
Blower	● A+
Vents	● A+

### ELECTRICAL

Power Windows	● A+
Infotainment	● A+
Camera	● A+
Parking Sensors	● A+
Interior Lights	● A+

This inspection reflects the visible and accessible condition of the vehicle at the time of inspection. Components not accessible without dismantling have not been evaluated. Findings are intended to assist buyers in making informed decisions and do not constitute a mechanical warranty or guarantee.

## QDRIVES VERIFIED CERTIFICATION

Q Drives Automotive Private Limited  
CIN: U45101TS2026PTC214865 GSTIN: 36AABCQ2618Q1Z1  
www.qdrives.net | +91 89779 86662 | Hyderabad, India



### INTERIOR

Seat Condition	● A+
Steering Wear	● A+
Pedal Wear	● A+
Flood Damage Indicators	<b>Not Found</b>

### OBD DIAGNOSTICS

Warning Lights	<b>Not Found</b>
Error Codes	<b>Not Found</b>
Diagnostic Remarks	<b>No error codes found</b>

### SERVICE & MAINTENANCE

Service History Status	<b>Complete</b>
Last Service Date	<b>14 May 2026</b>
Next Service Due	<b>34000</b>
Service Notes	<b>Regular service only</b>
Estimated Immediate Spend	<b>INR 0</b>
Estimated 12 Month Spend	<b>INR 5,000</b>

This inspection reflects the visible and accessible condition of the vehicle at the time of inspection. Components not accessible without dismantling have not been evaluated. Findings are intended to assist buyers in making informed decisions and do not constitute a mechanical warranty or guarantee.

## QDRIVES VERIFIED CERTIFICATION

Q Drives Automotive Private Limited  
CIN: U45101TS2026PTC214865 GSTIN: 36AABCQ2618Q1Z1  
www.qdrives.net | +91 89779 86662 | Hyderabad, India



## DEFECT PHOTO GALLERY



This inspection reflects the visible and accessible condition of the vehicle at the time of inspection. Components not accessible without dismantling have not been evaluated. Findings are intended to assist buyers in making informed decisions and do not constitute a mechanical warranty or guarantee.

## QDRIVES VERIFIED CERTIFICATION

Q Drives Automotive Private Limited  
CIN: U45101TS2026PTC214865 GSTIN: 36AABCQ2618Q1Z1  
www.qdrives.net | +91 89779 86662 | Hyderabad, India



### QDRIVES CERTIFICATION SUMMARY

Overall Grade	<b>A+</b>
Condition Score	<b>92.7 / 100</b>
Overall Condition	<b>● Excellent Condition</b>
Inspection Confidence	<b>High</b>
Buyer Recommendation	<b>Recommended Purchase</b>
Inspector Name	<b>Nihad</b>
Inspection Date	<b>31 May 2026</b>
Digital Signature	<b>8092EC9929BC</b>
Report ID	<b>QD-FU4HPH</b>

#### QDRIVES CERTIFICATION STATEMENT

This document certifies that the vehicle has been audited under the Q Drives Pre-Delivery Inspection (PDI) Programme. The contents reflect the visible and accessible condition of the vehicle at the time of inspection. Components not accessible without dismantling have not been evaluated. The document is digitally signed, tamper-evidence-protected, and independently verifiable using the QR code printed alongside.

#### INSPECTOR DECLARATION

I, Nihad, certify that the findings presented in this inspection report are based on the physical examination of the vehicle bearing registration TG10\*\*\*\*\*, performed on 31 May 2026. The inspection has been carried out using established procedures and tools available at the time of evaluation. Findings are intended to assist the buyer in informed decision-making and do not constitute a mechanical warranty or guarantee.



This inspection reflects the visible and accessible condition of the vehicle at the time of inspection. Components not accessible without dismantling have not been evaluated. Findings are intended to assist buyers in making informed decisions and do not constitute a mechanical warranty or guarantee.